

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

HAER
NY
23-ANTW.V
1-

HAER No. NY-191

WOOD'S GRIST MILL

South bank of the Indian River, approximately

.1 mile east of the breached mill dam

Antwerp Vicinity

Jefferson County

New York

Photographer: Rob Tucher

May 1988

- NY-191-1 VIEW TO WEST UP THE INDIAN RIVER, SHOWING BREACHED
MILL DAM (CENTER) AND GATE STRUCTURE (LEFT).
- NY-191-2 NORTH ELEVATION OF MILL STRUCTURE.
- NY-191-3 WEST ELEVATION OF MILL STRUCTURE.
- NY-191-4 INTERIOR VIEW OF MILL STRUCTURE FROM THE EAST END,
LOOKING TOWARD WEST WALL. MILL STONES AT LOWER CENTER.
- NY-191-5 INTERIOR VIEW OF MILL STRUCTURE FROM THE SOUTH SIDE.
MILL STONES ARE AT LOWER LEFT; BRIDGE ACROSS INDIAN
RIVER IS AT UPPER RIGHT.
- NY-191-6 VIEW LOOKING NORTHWEST SHOWING GATE STRUCTURE AT SOUTH
END OF SPILLWAY.
- NY-191-7 VIEW LOOKING EAST-SOUTHEAST THROUGH GATE STRUCTURE
TOWARD MILL STRUCTURE (LEFT REAR).